

Summary of ET Leader's Site Environmental Audit in the Reporting Month

Parameters	Date	Observations and Recommendations	Follow-up
Air Quality	8 Mar 2022	Reminder 1: The Contractor is reminded to increase watering for dust suppression during the demolition of sediment tank.	8 Mar 2022
Noise		NA	
Water Quality	23 Mar 2022	Reminder 1: The Contractor is reminded to prevent direct discharge of silt-laden water into the storm drain near the temporary transformer room.	23 Mar 2022
Chemical and Waste Management		NA	
Land Contamination		NA	
Ecological Impact	29 Mar 2022	Reminder 1: The Contractor is reminded to maintain and reinstate the bird curtain at the eastern site boundary.	NA
Landscape and Visual Impact	8 Mar 2022	Follow-up 1: Provide damp hessian to cover exposed roots underneath existing footpath for Tree No. T168 – T173 near site entrance.	8 Mar 2022
		Follow-up 2: Remove stockpile under dripline area for Tree No. T173 – T188 near site entrance.	
		Reminder 1: Avoid mechanical injury of crown and branches by sheet pile clamp during driving for Tree No. T168 – T173 near site entrance.	NA
	16 Mar 2022	Reminder 1: Contractor is reminded to keep planting area free of construction debris such as T020 & T022.	16 Mar 2022
		Reminder 2: Caution when work next to existing trees at CLP station area.	NA
	23 Mar 2022	Reminder 1: Please exercise caution when working near existing trees at (former changing room area) CLP area.	NA
29 Mar 2022	Observation 1: Trunk damage observed for Tree T252, tree maintenance work is recommended.	NA	
Permit / Licenses		NA	
Others		NA	