

Summary of ET Leader's Site Environmental Audit in the Reporting Month

Parameters	Date	Observations and Recommendations	Follow-up
Air Quality		NA	
Noise		NA	
Water Quality	26 Jan 2022	Observation 1: Silty deposit in gullies should be cleaned at Zone 2.	27 Jan 2022
		Observation 2: Mitigation measure should be provided to prevent direct discharge of runoff near the main entrance.	
		Reminder 1: The Contractor is reminded to de-silt the gullies near the main entrance.	
Chemical and Waste Management	11 Jan 2022	Reminder 1: The Contractor is reminded to provide drip tray for the chemical containers.	11 Jan 2022
Land Contamination		NA	
Ecological Impact		NA	
Landscape and Visual Impact		NA	
Permit / Licenses		NA	
Others		NA	